

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**



FIG. 1

PRIOR ART




FIG. 2
PRIOR ART








FIG. 3
PRIOR ART






FIG. 4

FIG. 5




FIG. 6




FIG. 7








FIG. 8A




SELF-SERVICE LUBRICATOR
IN FIG. 4




FIG. 8B



REQUEST
PRE-APPROVAL
↓
PRE-APPROVAL
IS GIVEN




REQUEST
PRE-APPROVAL
↓
PRE-APPROVAL
IS GIVEN



SELF-SERVICE LUBRICATOR
IN FIG. 4




FIG. 8C



REQUEST PRE-APPROVAL

PRE-APPROVAL IS GIVEN



SELF-SERVICE LUBRICATOR IN
FIG. 4

NOV 19 2003
MARK OFFICE

FIG. 9A








FIG. 9B



SELF-SERVICE LUBRICATOR
IN FIG. 4



FIG. 9C



SELF-SERVICE LUBRICATOR
IN FIG. 4

